

FIRE TECH SYSTEMS

MARUKUMMOOTTILBUILDING NO : 7/789

Thengana,Changanassery

FIRE PROTECTION ENGINEERS & CONTRACTORS

Contact No :9847507262

GSTIN/UIN:32BKVPR2188C2ZU

Date : 20/06/2025

FIRE AND SAFETY CERTIFICATE

This is to certify that SHREE VIDYADHIRAJA SEVA MISSION SCHOOL, KUDAKKACHIRA, Ward no XV, Building no : 2, Karoor Panchayath, Meenachil Thaluk, Kottayam Dist. Managed by Manager, Bhattacharya Samajam, Kudakkachira P.O, Kottayam is suitable and safe to function as a CBSE School on the Fire Safety Point of View. The surroundings and buildings have no fire risk. Necessary for First Aid Fire Fighting Precautionary measures have been provided at the buildings as shown below. So there is no safety risk, for the building, on the Fire Point of View.

Down comer system installed.

1. Hose reel	: 3 Nos.
2. Fire hydrant system	: 1 No
3. Fire extinguisher	: 5 Nos.
4. Carbon Dioxide Type 2 Kg	: 1 No.



Place : Changanassery

No & Date: 20/06/2025



PRINCIPAL
SHREE VIDYADHIRAJA
SEVAMISSION SCHOOL
KUDAKKACHIRA - 686 635
KOTTAYAM DIST.
AFFILIATED TO CBSE, NEW DELHI
AFFILIATION NO. 931086



MANAGER
SHREE VIDYADHIRAJA
SEVAMISSION SCHOOL
KUDAKKACHIRA - 686 635
KOTTAYAM DIST.
AFFILIATED TO CBSE, NEW DELHI
AFFILIATION NO. 931086